



Project: Power Generation Plant

The Problem

This Power Generation Plant was getting diminishing UT readings for these welds in their non-safety related piping.

They called RPT and Thortex for a solution.



The Solution

RPT and Thortex came up with a solution which required abrasive cleaning of the joint weld. We then taped off the area and applied 250 mils of **Thortex Metal-Tech XG** to reinforce the weld.

Thortex Metal-Tech XG was specifically developed for repairs requiring good mechanical strength where additional working time is essential during the application period.

RPT / RPT New York

12 Iron Bridge Drive • Collegeville, PA 19426
800.578.2772 • www.repairandprotection.com