



## Project Profile

# Skylight Replacement and Flashing



### The Problem

The existing fiberglass skylight lenses were deteriorated and leaking at the perimeters.

Numerous attempts at repairs had no lasting effect.

### The Solution

The surface was coated with a base coat of Poly-Tech Elastomeric Roof Coating.

Reinforcement mesh was embedded into the Poly-Tech.

A top coat of Poly-Tech was then applied to the entire area, resulting in functional, water-tight application.

