




Project: Metal Stair Refurbishment

The Problem

The stairs at this Battery Manufacturing Plant were being damaged because of their incidental exposure to sulfuric acid.

RPT was asked to repair them and protect them from further damage.



The Solution

RPT pressure washed the metal stairs and railings to remove dirt and rust. The heavily rusted areas were hand tooled.

One coat of **Thortex Corro-Tech GP** was applied followed by one coat of **Thortex Chemi-Tech UC** to protect the stairs against additional chemical attack.

Finally the stairs received a coat of **Thortex Grip-Tech** in Safety Yellow applied with aluminum oxide aggregate incorporated to provide a non-slip surface.

RPT / RPT New York

12 Iron Bridge Drive • Collegeville, PA 19426
800.578.2772 • www.repairandprotection.com