



## Profile: Concrete Repair & Protection



### The Problem

The project was to completely repair the concrete and coat the surface to provide protection against chemical attack.

### The Solution

The damaged concrete was reinstated using **Thortex Floor-Tech RS**. The entire concrete surface was coated with **Thortex Floor-Tech SP Primer**, the metal areas with **Thortex Uni-Tech MC Primer**, over which **Thortex Chemi-Tech CR** was applied.

Our safety surfacing system, **Thortex Grip-Tech**, was used for the edges of the islands.



**Repair and Protection Technologies, Inc.**

12 Iron Bridge Drive • Collegeville, PA 19426

800.578.2772 • 610.831.1910 (fax) • [www.repairandprotection.com](http://www.repairandprotection.com)