




## Project: Northeast Transportation Center

### The Problem

The stairs at this transportation center parking lot were severely damaged by weather and normal wear and tear. The company was eager to restore them to good condition. They wanted to prevent accidents. (Note the severe deterioration at the metal tread plates.).

RPT was called in.



### The Solution

RPT high pressure washed the concrete surfaces to remove all dirt, oil, contamination and loose debris. Then the chlorides had to be removed before the repair / coating process could begin..

The surfaces to be repaired were primed with **Thortex SP Primer** and rebuilt with **Thortex Floor-Tech RS**.

All existing coatings were removed, the entire surface primed with **Thortex SP Primer** and then two (2) coats of **Thortex Floor-Tech PU** were applied with a non-slip aggregate being incorporated into the first coat and then sealed in with the second coat.

**Thortex Floor-Tech PU** was chosen because of it's tough, durable finish that has excellent abrasion, impact and UV resistance.

RPT / RPT New York

12 Iron Bridge Drive • Collegeville, PA 19426  
800.578.2772 • [www.repairandprotection.com](http://www.repairandprotection.com)