



Project: Tunnel Refurbishment

The Problem

This underground tunnel carries cables under a shopping mall. Problems were developing because of water ingress and high humidity.

The high levels of humidity within the tunnel were affecting the cables and causing major problems in the mall itself.

The owners of the shopping mall decided that complete refurbishment of the tunnel area was required to overcome the problem..



The Solution

The floor and wall areas were treated with **Thortex Wall-Tech CWC**. This was where water penetration was occurring.

All joints were primed and filled with a mixture of **Thortex Flexi-Tech Primer** and **Thortex Seal-Tech SS**.

In total, almost 900 linear feet of tunnel was treated and the application system has been a great success.

RPT was selected for this project because of the success of the **Thortex Wall-Tech CWC** application at their other shopping centers.

RPT / RPT New York

12 Iron Bridge Drive • Collegeville, PA 19426
800.578.2772 • www.repairandprotection.com