



Project: 54" Pipe Wrap

The Problem

This WWTP's main in flow pipe – carrying 350 million GPD - had ruptured in several small areas.

RPT and Thortex were called in to affix the repairs during a narrow shutdown window.



The Solution

RPT applied **Thortex Cerami-Flex EG** at 120 mils over the prepared pipe surfaces. Nylon mesh was imbedded in the wet **Thortex Cerami-Flex EG**. A second coat of **Thortex Cerami-Flex EG** was applied at 60 mils over the meshed surfaces.

A final topcoat of **Thortex Cerami-Flex FG** was applied at 40 mils. The finished system was at 240+ mils.