



PROJECT PROFILE

PROJECT: CONCRETE BUND PROTECTION

THE PROBLEM

The concrete bund shown in this photograph had leaked resulting in diesel contamination of a nearby nature pond. The Environment Agency became involved and the client was held responsible for the clean-up operation.

The client was therefore anxious to find a high performance coating to repair and protect the bund to ensure a similar situation did not occur in the future.



THE SOLUTION

The bund area was steam cleaned to remove all diesel oil and then pressure washed. All surfaces to be coated were primed with Floor-Tech SP Primer and then Chemi-Tech CR was applied.

Chemi-Tech CR is a two component, solvent-free system with exceptional chemical and corrosion resistance. It has been designed to protect steel and concrete structures in aggressive environments.