



Project: Containment Area Refurbishment

The Problem

Severe erosion of the concrete plinths and containment area at a power station was caused by a sulphuric acid spillage.



The Solution

The concrete was rebuilt to its original specifications with **Thortex Grano-Tech** and **Thortex Floor-Tech RS**.

RPT then applied 2 Coats of **Thortex Chemi-Tech UC** to the entire area.

Thortex Grano-Tech is a high-performance mortar used as a heavy duty repair system for concrete and mineral surfaces.

Thortex Floor-Tech RS is a high-performance, solvent-free, epoxy resurfacing screed designed for use on concrete floors subject to abrasion and chemical attack.

Thortex Chemi-Tech UC is a high-performance, solvent-free coating used where exceptional resistance to chemical attack is required.