



Project: Corroded Recirculation Pump

The Problem

This severely corroded and rusted recirculation pump was taken out of service due to diminished flow.

RPT was called in to rebuild the pump.



The Solution

RPT removed the rust and corrosion and then used **Thortex Metal-Tech EG** to repair and rebuild the component.

RPT then coated the repaired pump with **Thortex Cerami-Tech FG** to protect it against further damage.

Thortex Cerami-Tech FG is a high-performance, fluid-grade engineering resurfacing compound that offers outstanding protection against, impingement, entrainment, corrosion and erosion and is designed for use in fluid flow environments.