



## Project Profile Off Road Tire Repair



### The Problem

This tire has suffered deep damage due to a heavy impact.

Due to the replacement cost for a new tire and the length of downtime required, the company wanted to undertake a high performance repair instead.

### The Solution

The surface was prepared by abrading with a wire wheel and all loose rubber was cut away.

The surface was primed with Flexi-Tech 60 EG was applied to all areas needing repair.

