



## Project: Chemical Manufacturing Facility

### The Problem

This chemical manufacturing facility needed to upgrade its plant to comply with OSHA regulations.

RPT and Thortex were called because of their successful track record for protecting their chemical tanks.



### The Solution

RPT blast tracked the floor and pressure washed the walls and steel. **Thortex Uni-Tech GP Primer** and **Thortex Wall-Tech UV** were applied to the walls and tanks.

**Thortex Corro-Tech GP** and **Thortex Wall Tech UV** were applied to the steel beams and pipes. **Thortex Floor-Tech SP Primer** and **Thortex Floor-Tech XSL** were applied to the floor. **Thortex Grip-Tech** yellow was applied throughout to meet their OSHA requirements.