



PROJECT PROFILE

PROJECT: Shower Block Refurbishment

THE PROBLEM

These showers, after years of use and attempts to paint over a problem, needed an upgrade.



THE SOLUTION

The ceiling was grit blasted to remove multiple layers of coatings, and to get sound substrate. Spalled areas were repaired with Wall-Tech LW. After preparation of the walls and floors, per Thortex recommendations, the entire area was refurbished using Wall-Tech UV. The floor was made a different color to break up the appearance, and to add contrast to the area. The customer is considering doing quite a few more of these, and individual showers as well.

