





Project Profile Valve Stem Repair

The Problem

Automatic valve stems had become worn over time due to the aggressive service environment at this fabrication plant.

The company sought a high performance engineering repair solution.



The Solution

Metal-Tech RG was used to effect a rapid engineering repair.

Metal-Tech RG is a rapid curing, polyurethane metal repair compound designed for the quick turnaround of metal repairs.