



Project: WWTP Concrete Digester

The Problem

This WWTP's digester cracked and methane gas was leaking into the atmosphere. They needed an emergency repair and called Repair and Protection Technologies for help.



The Solution

After cleaning the surface with a non-residual solvent, we repaired the crack with **Thortex Metal-Tech RG**.

Once the gas was contained, we wrapped the entire structure with 10mm of **Thortex Metal-Tech EG** and two (2) layers of embedded mesh. We completed the project by top coating with **Thortex Flexi-Tech 80 EG** to add additional impact resistance in this high traffic area.

RPT / RPT New York

12 Iron Bridge Drive • Collegeville, PA 19426
800.578.2772 • www.repairandprotection.com